HS-AS Studs

adapters



Adapters to connect accelerometers to machine faces.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2		
HS-AS006	Quick Fit Female	1/4"-28 UNF Male		1
110 7.0000	Quiote i e i e i i e i	74 20 0111 Maio		
HS-AS009	M6 Female	M8 Male	(-)	
			61	
HS-AS026	10-32 UNF Male	M6 Male	1	
HS-AS028	Quick Fit Female ½" UNC	1/4"-28 UNF Male		8
HS-AS030	M8 x 1.25 Female	1/8"BSPT Male		1
HS-AS032	Quick Fit Female	M8 Male		1
HS-AS039	Quick Fit Female ½" UNC	10-32 UNF Male		1
HS-AS045	Quick Fit Female	M5 Female		
HS-AS088	Quick Fit Female 9/16" UNC	M5 Female		9
110 40000	0/0"	0/0" NDT M 1	(4)	8
HS-AS092	3/8" UNF Female	3/8" NPT Male		
HS-AS103	1/4"-28 UNF Female	1/4" NPT Male		
HS-AS107-M6	M6 Female	M6 Male		
110 10444	MO Ferrole	MO Family	•	
HS-AS111	M8 Female	M8 Female		
HS-AS119	1/4"-28 UNF Female	1/4"-28UNF Male	(E
HS-AS121	1/4"-28 UNF Female	3/8"-16 UNC Male		0
ПЭ-АЭ 12 Г	/4 -20 UNF Female	3/0 - 10 UNC Male	-	6



www.ie-central.com



