HS-AS Studs Quick Fit threads



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

| Part No. | Connection Point 1 | Connection Point 2 | | |
|----------|----------------------------|--------------------|-----|-----|
| HS-AS001 | Quick Fit Male | Glue Face | | |
| | | | | |
| HS-AS002 | Quick Fit Male | M8 Male | | |
| | | | | • |
| HS-AS003 | Quick Fit Male | M6 Male | | |
| | | | | |
| HS-AS004 | Quick Fit Male | 1/4"-28 UNF Male | 1 | |
| | | | | A |
| HS-AS007 | Quick Fit Male | M10 Male | | (E) |
| | | | (9) | |
| HS-AS010 | Quick Fit Male | M8 x 1.25 Female | | • |
| | | | (4) | |
| HS-AS011 | Quick Fit Male | M6 x 1 Female | | • |
| | | | | |
| HS-AS012 | Quick Fit Male | 1/4"-28 UNF Female | | () |
| | | | | |
| HS-AS013 | Quick Fit Male (9/16" UNC) | Glue Face | (4) | |
| | | | | |
| HS-AS018 | Quick Fit Male (½" UNC) | Glue Face | (2) | |
| | | | | |







HS-AS Studs Quick Fit threads

| Part No. | Connection Point 1 | Connection Point 2 | | |
|----------|-------------------------|-----------------------------------|---|---|
| | | | | 4 |
| HS-AS033 | Quick Fit Male | M8 x 1 Male | | |
| | | | | |
| HS-AS034 | Quick Fit Male (½" UNC) | M6 x 1 Male | | |
| | | | | 4 |
| HS-AS037 | Quick Fit Male (½" UNC) | M8 x 1.25 Male | | |
| | | | | |
| HS-AS041 | Quick Fit Male | 3/8" BSP | | |
| | | | | |
| HS-AS049 | Quick Fit Male | 1/8" BSP | | |
| | | | | |
| HS-AS064 | Quick Fit Male | M5 Male | | |
| | | | | |
| HS-AS065 | Quick Fit Male | Glue face and M6 x 1 Female | (| |
| | | | | 6 |
| HS-AS072 | Quick Fit Male | M8 x 8mm Male | | |
| | | | | |
| HS-AS078 | Quick Fit Male | Glue Face in 316L Stainless Steel | | |
| | | | | |
| HS-AS108 | Quick Fit Male | M12 Male | | |
| | | | | |
| HS-AS120 | Quick Fit Male | 1/4"NPT Male | | |
| | | | | 6 |



